** Caution!! After this functions, please keep idle running until ABS lamp turned off.
(Approx. 5 min)

** If the SAS lamp is ot turned off, you need to
SWASM(Steering wheel angle sensor module) SAS reset and relearn functions.

1. Select correct system

2. Select [Special function].

3. Select [Steering wheel angle sensor learn].

4. Note.

5. Complete.