

HOLDEN COMMODORE
REAR LAMP FAILURE WARNING SYSTEM BULB
RELEARN PROCEDURE

If the battery has been disconnected and power has been interrupted to the Body Control Module (BCM) it is essential to relearn the rear lamp system to prevent globe failure.

Ensure battery is fully charged and alternator output is correct before carrying out the following procedure:

1. Ensure all rear light bulbs are working. Replace/repair any faulty bulbs/wiring.
2. Turn ignition OFF, parking lamps OFF and ensure stop lamps are OFF.
3. Remove and reinstall fuse F31 or (model relevant fuse) from the engine compartment relay housing, to reset BCM.
4. Engine must be started and idling.
5. Switch ON the parking lights.
6. Wait 5 seconds.
7. Press and hold the brake pedal.
8. Wait 5 seconds.
9. Switch OFF the parking lamps and wait 5 seconds.
10. Bulb relearn is now complete, turn engine OFF and release the brake pedal.