



1. Select [ABS/ASC/ASTC/WSS]




2. Select [Special function]



3. Select [Sensor calibration]



4. Select [SAS Calibration]



** G-scan will display some sensor data for that system.

** Press [OK] to calibrate.

5. Complete.



** On some types of SAS you may need to turn IG.OFF and IG.ON to complete the procedure

** On some types of SAS you may need to perform [All sensor calibration] to complete the install.

** On some types of SAS you may need to perform the [SAS initialization] function within [Steering angle sensor] system.