




1. Select General>ALL>16 pin connector>00->Engine




2. Select [Special function]



3. Select [Idle adjustment with A/C on]




4. Warning message




- G-scan will show the setting value already programmed.

5. Setting value#1



6. Setting value#2



7. Setting value#3



8. Setting value#4



9. Setting value#5

