



Select to [Benz] > [V-Class/Transporter] > [Sprinter 2006 - Present[W906]]
> [Diesel engine] > [CDI4]




Select to [Special function]




Select to [Adjustment of injector injection quantities]




Note 1



Note 2



Input injector masking



Confirm injector masking

CDI4(Comon rail diesel injection) > Adjustment of injector injection

Step 5 - Injector marking is 67CBG87

Do you want to continue?

OK Cancel CYL3 CYL4 Exit