1. Select [Maintenance>Oil Service(ESI/SRI Resetting)]



2. Select [Special function]

Diagnosis Menu > Oil Service(ESI SRI Reset)	+ O
 Special Function 	•
•	Copy right G-Scan Oceania

3. Select [ESI Resetting]



4. Note



5. ESI Resetting Status

 Oil Service (ESI SRI Reset) > ESI Reset 	+ 0
ESI: Resetting ESI (Extended Service Interval) [1] Reset [2] Warning active	
It may be necessary to cycle the key before the Select the function number please.	he service warning is cleared.
Item	Current value Unit
ESI value status	Warning
[1] [2] Cancel	Copy right G-Scan Oceania

6. ESI Reset complete

Oil Service(ESI SRI Reset) > ESI Resetting		+ 0
ESI: Resetting ESI (Extended Service Interval)		^
Adaptation success		
	Copy right	
	G-Scan Ocean	na

7. ESI Resetting status

 Oil Service(ESI SRI Reset) > ESI Reset 	÷ 0
ESI: Resetting ESI (Extended Service Interv [1] Reset [2] Warning active	val)
It may be necessary to cycle the key before Select the function number please.	e the service warning is cleared.
Item	Current value Unit
ESI value status	Reset
	Copy right
[1] [2] Cancel	G-Scan Oceania