# 1. Select [VZ -> Body -> PIM(Powertrain Interface Module)] menu



## 2. Select [Special function]

👝 Diagno:	sis Menu > PIM(Powertrain Interfac	e Module)	+	Ö,
• /	DTC Analysis		Þ	
	👄 Data Analysis		►	
	Flight Record Revie	W	►	
	Actuation Test	Copy right	Þ	
•	Special Function	G-Scan Oceani	3	-

# 3. Select [PIM link to ECM(V8 GEN IV)]

😑 Diagnosis	Menu > PIM(Powertrain Interface Module)	+ <b>D</b>
•	PIM Configuration Coovering	) ht
•	Program VIN G-Scan Oce	ania
	👄 Reset PIM	►
*	PIM link to ECM(V6 GEN IV)	•
•	PIM link to ECM(V8 GEN IV)	•

#### 4. Notice



#### 5. Notice

PIM(Powertrain Interface Module) > PIM link to EC	:M(V8 GEN	IV)	+ O
Input security code(4-digit number) :	1	2	3
	4	5	6
Copy H3N G-Scan Oceania	7	8	9
	<-	0	Enter
OK Cancel			

#### 6. Notice

PIM(Powertrain Interface Module) > PIM link to E	CM(V8 GEN IV)	F 🖸
Turn ignition off.		~
Press [OK] to next.		
	Copy right	
G	Scan Oceania	
OK Cancel I		

## 7. Notice



### 8. Notice

PIM(Powertrain Interface Module) > PIM link to ECM(V8 GEN IV)	+ 🖸
Completed	
Copy dent	
G-Scan Oceania	