Nissan Anti Theft System (NATS 2) * technical tip

If a key that has been previously programmed to a vehicle has been de-programmed and is not starting the car, try the following:

Insert the ignition key into the ignition and turn 'On' for 5 seconds

Turn ignition key 'OFF'

Turn ignition key 'ON' for 5 seconds

Turn ignition key 'OFF'

Turn ignition key 'ON' for 5 seconds

*This will override the NATS system and allow the car to start. If there is no problem with the system, the ECU will recognise that the system is ok and it will continue to allow the car to start after this ignition cycle without a problem.

If a new key is to be programmed, this must be done in the Anti Theft System using a diagnostic scan tool.