



2. Select [Special function]



3. Select [Cabin filter regeneration]





5. Notice





	7.	Notice
--	----	--------



Injection > Cabin filter regeneration	0 + D			
IMPORTANT:	~			
- it is essential to switch off the air conditioning s (risk of engine failure) and all other electrical	system Copy right			
consumers,	G-Scan Oceania			
- it is essential to check the engine oil level to prevent any risk of engine racing, it should be between the minimum level and the mid-way level marks on the dipstick,				
Next Cancel				

Injection > Cabin filter regeneration		+ 🗅		
In an emergency: regeneration can be halted by two short presses on the vehicle start button (less than 3 secs). Switch off the ignition and wait one minute before switching it on again. The command will be terminated if the engine is switched off for more than one minute.				
IMPORTANT - in the course of any regenera - do no disconnect the diagnostic tool, - do not move the vehicle. - do not depress the brake pedal.	ation operation:			
	G-Scan Oceania			



11. Notice





Injection > Cabin filter regeneration	+ 0			
Important : Engine oil service essential (EXCEPT if a second regeneration is required).	<u>^</u>			
- Switch off the ignition and wait for the loss of communication message to appear on the diagnostic tool(Maimum time 9 minutes).				
- Use command 'Programming reinitialisation' and select 'After particle filter regeneration with diagnostic tool'.				
- Switch off the ignition and wait for the loss of communication message to appear on the diagnostic tool(maximum time 9 minutes				
- Erase the faults.				
OK Cancel G-Seath Gegen				