




1. Select [PCM] system




2. Select [Special function]




3. Select [Fuel injector pilot correction learn]




4. Notice



5. Notice




6. Notice




** G-scan will show the precondition factor. Please check that sensor values


7. Notice



8. Notice




9. Notice



** This procedure take about 400 seconds.

10. Turn ignition off



11. Turn ignition on

